BOMBARDIER

April 19-2022

SAP Supplier no: 139588

TESTIA MEXICO S. DE R.L. DE C.V.

SAP no 1000068274

Edificio Espacio Ejecutivo Oficina 9, Avenida Fray Luis de Leon 8051, Queretaro 76090, Mexico

Attention: Marc Mahé/ Inspection Manager

Subject: Name change

Bombardier Quality is pleased to inform you that your organization name change of Testia Mexico S de RL de CV , at the above noted address has been completed .

Your approval remains as a class A – subcontractor with BAPS 176-019EDDY CURRENT INSPECTION Limited to provide Inspection Services to LATECOERE located at Address: Pierre Georges | Latécoère #1, Col. La Manga, C. P. 83220, Hermosillo, Sonora, Mexico, Only.

This approval will be maintained on the condition that your company continues to comply with QD 4.6-40, Quality Requirements for Suppliers, and maintains acceptable product delivery performance.

Bombardier Quality may elect to audit your facility at any time during or prior to any contract, in order to:

- Assure continuing compliance with contractual and quality requirements.
- Investigate any quality problems and ensure that effective corrective action measures are implemented.

Your approval status will be periodically reviewed. Based on supplier performance, the approval status of your facility may be revised. It is Bombardier's policy to purchase only from approved suppliers who meet our standards of quality and reliability. We look forward to building a mutually beneficial and lasting relationship, driven by a desire for continuous quality improvement

Sincerely yours,

Manon Carbonneau

Quality Analyst Supplier Quality Assurance

Bombardier I 400, Côte-Vertu West I Dorval, Québec I H4S 1Y9 www.bombardier.com Tel: 514-855-5000 Fax: 514-855-7401